









Display Bar Table + Storage

Part # T39-DISPLAY XX+XX

21-1122

PARTS				
				
X12 (M6 x 12) A	X6 (M6 x 40) B	X2 (M6 x 40) C	X16 (M7 x 50) D	E




Do not over tighten.
Do not use power tools to assemble.

Display Bar Table + Storage

Part # T39-DISPLAY XX+XX


21-1122

3




C x 2

4




B x 6

5



D x 16

6



Do not over tighten.
 Do not use power tools to assemble.